

"PLASSY" (RMC) Information has been received from the Glasgow Surveyors to the effect that the refrigerating fan motors for this ship, comprising two 25" axial flow $3 \frac{1}{4}$ Horse Power variable speed motors were ordered by Messrs. L. Sterne & Co., Ltd. from Messrs. Keith Elckman Ltd., London to Lloyd's survey on Order No.134150 dated 29th May, 1952 and were delivered direct to the vessel. No certificates are, however, available in the Glasgow Office and I shall therefore be glad if you will forward copies for record purposes.

126027, 28, 29, 34, 36. As recommended.

5842 "PERIM" RMC. As recommended. I shall, however, be glad to receive your confirmation that the insulation on No. 4 hold tank top has been dealt with.

IB 4491, 92, 93, 94, 95, 96. As recommended.

© 2020

Lloyd's Register
Foundation

Cont/.....