

Extract from Hull. Classing Letter. 30.12.52.

LASSEY" RMC. 58859. As recommended. I shall be glad if you will state the thickness of the insulation fitted to sides, overheading and floors of chambers which are given as 8", 8" and 6" respectively on the plan but information in regard thereto has been omitted from the First Entry report.

I shall be glad if you will confirm that the insulation thickness at bulkhead No. 36 is 4" on the fore and aft sides, as this is shown on the drawing to be 8" on the aft side and 2" on the forward side.

Cont/...

HULL (Continued)

(30.12.52)

At the same time I shall be glad if you will furnish the refrigerating fan motor test certificates for record purposes in this Office.

58842. "PRINCESS ELIZABETH". This vessel has today been classed ~~100~~ A.1. "Motor Trawler" together with the appropriate notations as recommended by you.



© 2020

Lloyd's Register
Foundation

0421 2/2