


Mr. Cook

You will notice the difference in M.N.  
Perhaps this may affect the fee

X

HP 502

M.N. 714



© 2020

Lloyd's Register  
Foundation

004630-004634-0218

tonnage of the engine room spaces below the Upper Deck is 825.04 tons, and the tonnage of the total spaces framed in above the Upper Deck for propelling machinery and for light and air is 254.74 tons.

Copy

1m.2.45.

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME

Patella

REPORT.....

No.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Oil Engine

No.

22 9/11

584

Lloyd's Register Foundation