

## LLOYD'S REGISTER OF SHIPPING

Port Curacao, N.A.Date 17th June, 1967.This is to Certify *that I have*surveyed the N.V. "PATILLA" 8277 gross tons of Londonfor Repairs on 12th June 1967 and subsequently while lying  
lying afloat at this port.

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all repairs recommended by me have been completed to my satisfaction, also that I am recommending that she be retained as classed without fresh record, subject to bottom rivets in starboard No.6 wing tanks being specially examined and dealt with as found necessary at next Drydock Survey and to any other outstanding condition of class being dealt with as previously recommended.

*(Signature)*  
Surveyor to Lloyd's Register of Shipping

## KEY TO ABBREVIATIONS

AS Annual Survey  
BIS Biennial Survey  
DS Docking Survey  
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey  
SS(Dr) Hull Special Survey (Drilling)  
SS(M) Hull Special Survey (Modified)  
CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of the Surveyors, or other Officers, Servants or Agents of the Society."