

JW
Ship's name

"PATELLA"

Port

No.

The class is subject to set in shell plates G.11, H.11 & 12 (p. from a.) being specially examined and dealt with as necessary next drydocking and to a bower anchor and 105 fathoms of chain cable being supplied as soon as possible.

ACTION is DEFERRED for a short time for equipment.

There is an S.R.L. Appendix note.

In a cable dated 17.3.67 the Lisbon Surveyors state that the missing equipment has been placed on board but not verified.

IN VIEW OF THIS IT IS SUBMITTED the ship is eligible to remain as classed, subject to set in shell plates G.11, H.11 & 12 (p. from a.) being specially examined and dealt with as necessary next drydocking and to a bower anchor and 105 fathoms of chain cable (supplied Lis.1,67) being verified at the earliest opportunity.

As Now, Subject.
Amended.

IN S.R.L. APPENDIX
H.10 & 13, J.15 (s.f), H.7 & 8, J.10
(p. amids) slightly indented.

24.12
29-3-67



© 2020

Lloyd's Register
Foundation