

21.12
COMMITTEE LDN
MOMPSE

CCO 6.12

TELEX CURACAO
U
TELEX CURACAO

TELEX CURACAO
U
TELEX CURACAO
X

CONNECTED

16.16
DAMMERS CU17
O

TELEX CURACAO
U

TELEX CURACAO
X

CONNECTED

16.18
DAMMERS CU17
O

TELEX CURACAO
U

TELEX CURACAO
X

TELEX CURACAO
U

COMMITTEE LDN

CURACAO, JANUARY 2ND, 1967.
TO : LLOYDS REGISTER OF SHIPPING LONDON - TELEXNO.24305
FROM: H. SLUITER C/O SHIPYARD - CURACAO, TELEXNO.CU7

M/V ''PATELLA'' L.R. 527154

LOST PORT ANCHOR AND TEN LENGTHS OF CHAIN CABLE.

AVAILABLE FOR REPLACEMENT SHIP'S SPARE ANCHOR AND THREE
LENGTHS OF CHAIN CABLE.

PLEASE ADVISE WHETHER ACCEPTABLE AND WHICH ARRANGEMENT
RECOMMENDED.

OWNERS WILL CONTACT YOU.


SLUITER REGISTER CURACAO

COMMITTEE LDN
CALL ENDED PLSE CLOSE AND CHARM

TELEX IN

CT = 300 fms.

004630-004634-0281



© 2020

Lloyd's Register
Foundation

Repts.
SR

Submitted surveyor be
informed that 3 lengths of chain
cable be transported from the starboard
side and connected to the 3 long the lower
replacement cable to which the shore bow
anchor should be fitted. Thus having two
working cable anchors respectively. 7 and 6 lengths of
chain cable has been seen (shown).
The wood of anchor has been seen (shown).
informed per telephone and shown.

20.3/1/67



© 2020

Lloyd's Register
Foundation