

30 OCT 1951

NN "HEIMDAL"

Received from
Chief Ship Surveyor:

SHIP'S NAME: "K E R M A"

REPORT: Mch. No: 14738

Outstanding Conditions of Class: Subject to permanent repairs to (fractured) D.B. tank top plating in after hold, and to indented shell plates H.9, G.8 & 9 etc. (s.s.a.) and E.5 (p.s.f.) being dealt with, all by next Special Survey.

Endorsement of Class (B) (As before ~~or None.~~)

Nature of Present Survey: Docking & Damage repairs as above.

Recommendation: SUBMITTED record of docking 10,51 be assigned, without special conditions, but with Endorsement (B).

10,51 Mch. Without.

ENDORSEMENT/OF CLASS (B).

Indents in shell plating (p & s).

SPR
27-10-51.



© 2020

Lloyd's Register
Foundation

004635-004641-0249