

"HILARY"
Liverpool F.E. 149787.

The Liverpool Surveyors report the satisfactory installation of a new low temperature chamber cooled by the original refrigerating plant on above ship.

Their report has been examined and the temperature qualification recommended by them is in order, viz: "to maintain temperature 40°F. in Nos. 4 & 5 TD spaces, or minus 5°F. in the low temperature chamber when remaining spaces not refrigerated, with sea temperature 85°F. maximum."

†

11th August, 1958.

Shu

NOTE.

The alterations do not affect the No.4 Lower Hold installation which remains as now in R.B.



© 2020

Lloyd's Register
Foundation