

SHIP'S NAME

"PORT WYNDHAM"

PORT

LON

No.

155362

LAST SURVEY DATE

16.11.65.

- CLASS IS SUBJECT TO
1. Port aft auxiliary engine No.3 cylinder jacket (M.L. 8.64) being examined before the end of 11.65.
  2. Port forward auxiliary engine No.4 entablature (M.L. 10.64) being examined by end of 5.66.
  3. Outboard air compressor cast iron combined LP/MP piston be specially examined and dealt with as necessary before the end of 11.65.
  4. Starboard main engine No.1 forward side crosshead pin be specially examined and dealt with as necessary before the end of 11.65.
  5. Repaired oil end casting of aft O.F. transfer pump be re-examined and dealt with as necessary on vessels return to U.K.

Items Nos. 1 & 3 examined, found to continue efficient & limit to be extended to end of 11.66.

Item 4. Pin renewed item to be deleted.

Item 5. Specially examined & it be recommended it be again examined by end of 5.66.

Docking W/R P  $\frac{1}{8}$ "  
S  $\frac{3}{16}$ "