

PT

24 MAR 1966

Ship's name "GLOUCESTER"

Port LON

No. 155843

Last survey date 4.2.66

Class is subject to

indented shell plate J.1 (p.s.f) and internals in way,
 to wasted bulkheads 1/2 and 2/3 in way of upper tween deck
 and to No.4 upper tween deck chocks and shell plate C.14 (p.s)
 in way of No.5 lower hold (doubled) being specially examined
 and dealt with as necessary by the Special Survey and to stem
 and stem plating being specially examined and dealt with as
 necessary next drydocking. ACTION is DEFERRED for S.S. by 7,66.
S.R.L. Appendix (as before ~~or 1965~~)

Surveys due

SPECIAL SURVEY (D) due 7,65. Postponement until
 7,66 approved 25.10.65 following a satisfactory
 G.E.

Nature of present survey (afloat and in drydock)

Docking.
 Temporary repairs to damage (contact).
 Wear and tear repairs.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed by

Recommendation

SUBMITTED record of DS 2,66 be assigned,
 subject as above, but ACTION continue to
 be DEFERRED for Special Survey by 7,66.

DS 2,66 subject.

IN S.R.L. APPENDIX

Shell seam of 'J' & 'K' strakes in way of
 frs.109/111 (p.s.f) indented.
 (Sternframe at top gudgeon E.W. 7,61).
 Indents in shell plating (p & s).

TO NOTE		TRO
S. PLANS	S. RESEARCH	S. DEVELOP.
FREEBOARD	E. REPORTS	PUBS.

2020
Ddt. 25/2/66