

Ship's name "CONSULATE"
Ex "GLOUCESTER"

Port Hul.

No. 71593

Last survey date 22.6.66

GB Class is subject to For conditions of class see previous
endorsement.

ACTION is DEFERRED for S.S. by 7,66.

S.R.L. Appendix (as before ~~XXXXXXXXXX~~)

Surveys due SPECIAL SURVEY (D) due 7,65. Postponement until
7,66 approved 25.10.65, following a satisfactory G.E.
Further postponement until 10,66 approved 20.5.66
provided a satisfactory G.E. is held.

Nature of present survey (afloat ~~XXXXXXXXXXXX~~)

General Examination as above.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS

TO NOTE		TRO
S. PLANS	S. RESEARCH	S. DEVELOP.
FREEBOARD	E. REPORTS	PUBS.

SS proposed to be completed by

See Committee Minute.


Recommendation

SUBJECT to indented shell plate J.1 (p.f) and
internals in way, to wasted bulkheads 1/2 and 2/3 in way of
upper 'tween deck and to No.4 upper tween deck chocks and
shell plate C.14 (p) in way of No.5 lower hold (doubled)
being specially examined and dealt with as necessary by
the Special Survey and to stem and stem plating being
specially examined and dealt with as necessary next
drydocking but ACTION continue to be DEFERRED
for Special Survey.

SUBJECT
AMENDED.

S.R.L. APPENDIX NOTE (AMENDED)

Shell seam of 'J' & 'K' strakes in way of
frs.109/111(p.f) indented.
(Sternframe at top gudgeon E.W. 7,61).
Indents in shell plating (p & s).



Ship's name "CONSULATE" Ex "GLOUCESTER"
 No. 71593
 Last survey date 22.6.66
 For conditions of class see previous endorsement.

ACTION IS DEFERRED for S.S. by 7.66.


IT IS FURTHER SUBMITTED postponement of the Special Survey until 10.6.66 merits approval. Further postponement until 10.6.66 approved 20.6.66 provided satisfactory G.E. is held.

Nature of present survey (XXXXXX)

General examination as above.

Yes/No/None

is interim certificate transfer items outstanding if any for SS



ALL ITEMS


SS proposed to be completed by See Committee Minute.

Recommendation

SUBJECT to indented shell plate 3.1 (p.f.) and internal in way, to wasted bulkheads 1/2 and 2/3 in way of upper 'tween deck and No. 4 upper tween deck chocks and shell plate 0.14 (p) in way of No. 5 lower hold (doubled) being specially examined and dealt with as necessary by the special survey and to stem and stem plating being specially examined and dealt with as necessary next drydocking but ACTION continue to be DEFERRED for special survey.

Shell seam of 'K' strakes in way of (Sterntrams at top Engcon E.W. 7.61). Indents in shell plating (p & a).
 APPENDIX NOTE (AMENDED)
 SUBJECT AMENDED.

P.T.O.



© 2020