



LLOYD'S REGISTER OF SHIPPING

4th Floor Shurdut Bldg., Intramuros, Manila, Philippines

Telegrams: REGISTER, Manila

P. O. Box 1447

7 JUL 1965

Telephone: 3-15-78

AIR MAIL

July 3 19 65

ERS/ks

The Secretary,
Lloyd's Register of Shipping,
71, Fenchurch St.,
London, E.C.3

Dear Sir,


R
NAB/GDF

M.S. "TOMAR"

With reference to your letter of 23rd April, 1965 to The Surveyors, Oslo, copied to me, I wish to advise that I attended on board the vessel today and was advised by the Chief Engineer that the Donkey Boiler Survey had been carried out in Bangkok and referring to the Machinery Survey Book on board it appears that the examination was carried out on the 25th June, 1965 and the Safety Valves adjusted under steam on the 27th June, 1965 together with the Oil Burning and Steam Smothering arrangements tested and found in order.

I was advised that Mr. Winn was in hospital at this time and a Mr. Sven Marquardsen, Surveyor to Norske Veritas, had acted in his stead. There was no certificate on board covering the survey.

Yours faithfully,


E.R. SANDERSON

c.c. The Surveyors,
Hong Kong

© 2020

Lloyd's Register
Foundation

004684-004692-0211