

23 JUN 1966

Ship's name "PAKISTAN PROMOTER" Port CHG No. 918

Last survey date

Class is subject to :-

20.4.66.

1. Propeller rubber ring sealing ring gland studs being examined & dealt with and stern bush lining being renewed by 6.65.
2. Fwd. boiler not to be used until defective plain tubes have been renewed.
3. M.L. repairs to S. feed pump be specially examined by 7.65.

Class suspended - Surveys overdue.

Ship proceeding from CHG to KRH for reinstatement of class - see cables 2.6.66 & 3.6.66.

MBS now commenced.
SPS held.

It is submitted that this vessel is eligible for THE RECORDS SPS 4.66. & MBS 4.66, when the Boiler Survey completed and class reinstated, Subject to above and to P. & S. boiler air heater tubes, being renewed at KAR. where now proceeding.

G.A.
23.6.66.

Conclude G.E. will be held and P. & S. boiler safety valves adjusted before vessel sails.

TO COMPLETE MBS.

Fwd. & centre boilerS to examine throughout, safety valves of all 4 boilers to be adjusted under steam, saturated steam pipes in fwd and centre smoke boxes to be examined as per Rules, Oil burning system and remote controls examined working as per Rules, and subject item (2) above being dealt with.

and as now recommended.