

MEMORANDUM

From : LLOYD'S REGISTER OF SHIPPING, 71, FENCHURCH STREET,
LONDON, E.C.3.

(Ref. R.)

To : The Surveyor(s) at KARACHI

Date : 2nd September, 1964.

Vessel's Name: S.S. "PAKISTAN PROMOTER"

SEI/CB

25 SEP 1964

[Handwritten signature]

QUESTION

Machinery condition of class and Main Boiler Survey due 7.64, see my letter dated 13th July, 1964 and previous correspondence.

Reference entry for vessel in your Weekly Return dated 24th July please state position regarding satisfactory check by a diver of the propeller gland ring stubs and weardown, also the Main Boiler Survey.

[Handwritten signature]

ANSWER

Date:— 21st September, 1964.

The Main Boiler Survey has been commenced at this port. The wear down of sternbush lining has been checked and was found to be 7.2 mm. The propeller rubber seal ring gland studs were examined and found to continue efficient.

The Owners state that the drydock at Karachi will not be available before the middle of December next and that they made definite arrangements to have the ship drydocked at that time.



© 2020

Lloyd's Register
Foundation

[Handwritten signatures and initials: JVB, AW, and others]

004684-004692-0386

ER