

COPY

LLOYD'S REGISTER OF SHIPPING

21181



Port..... SINGAPORE

Date..... 6th August 1968

This is to Certify that ^{we} ~~it~~ have surveyed part of the machinery of the S.S. "TEXACO GLASGOW" gross tons 11847 of LONDON for defect in the outboard auxiliary generator whilst the ship was afloat at this port on 27th February 1968

and that all ~~our~~ ^{our} recommendations have been carried out to ~~our~~ ^{our} satisfaction. ~~are~~ ^{We} reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained ~~and the following~~ ~~survey records assigned~~ without fresh record of survey subject to any outstanding conditions of class being dealt with as previously recommended.

Parts now examined:—

[Signature]
Surveyor to Lloyd's Register of Shipping
(A.J. DIX AND D.M. DENTON)

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150° F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers, Servants or Agents of the Society."