

Sangola

bal. 14,157.

Two additional refrigerated chambers have been fitted to this vessel and to complete this part of the installation satisfactory cooling tests require to be carried out. It is stated this will be done at Singapore.

Submitted action be deferred.

R. S. not advanced.



© 2021

W.L.S.
Hoyd's Register
Foundation

6.7.50

004698-004702-0292