

21st April, 1953.


ROTTERDAM

6007,54,60,79,86,88,89,98,106,11,13,16,17,
16,32. As recommended.

"CAPE ST. DAVID". Further to my Classing Letter of the 14th instant, I have to inform you the Owners state they have no objection to the acceptance of the electrical arrangements as now fitted and accordingly the Committee have assigned to the vessel records of Drydocking and Special Survey as recommended by you.

6118 "WALVIS BAY". As recommended, except that a record of crewshaft Survey 2,53 has been assigned. I shall be glad if you will furnish the certificate for the new rudder head now fitted as this has not come to hand with your report.

6127 "MARGO". As recommended. It is concluded the boiler blow down pool piece was renewed at this time, as recommended by the Vancouver Surveyors in October last, but I shall be glad if you will confirm this.



© 2020

Lloyd's Register
Foundation