

POSTPONED SURVEYS

..... m.s.s. "MILO"..... No..... in R.B.

- 1944 Tonnage..... Owners.....

Port of Registry.....

Last docking date..... 8,56......

due Special Survey due 7,57......

Screwshaft Survey due 11,57......

The Class is subject to bottom shell plating in way of (wasted) to be examined and dealt with as necessary by next Special Survey (due 7,57) and permanent repairs to after peak tank plating at the Special Survey.

l to be.....

The Owners stated on the 11th June 1957 that the ship would be laid up and offered for sale locally. The Committee agreed on 17th October, 1957 that the class should remain undisturbed it is concluded that the outstanding conditions of class would be dealt with before recommissioning.

It is now stated that the vessel is still laid up.

Handwritten signature and date:
18.7.57

Surveyors' recommendations.....

Committee's Minute.....

FRIDAY - 1 AUG 1958

Handwritten: laid up

Handwritten: Survey overdue 757

Noted for Header

NOTED FOR REPAIRS

2021

Lloyd's Register Foundation

004769-004777-0015

004769-004777-0019