

MONTREAL OFFICE

Re:-

MONDOC

Report No. Mt1. 13438

re of Survey:-

Part MBS and Part ES

Following remains to complete the survey:- Safety valves to be adjusted under steam.

Vessel not yet in commission.

Recommendations:-

The Vessel appears eligible to remain as classed ~~without~~ with fresh record of MBS 2,60 when the Survey is complete.



© 2021

Lloyd's Register
Foundation

June 3rd, 1960.