

LLOYD'S REGISTER.

Lloyd's Register of Shipping,

RECEIVED
123 OCT 1922

3, Steinhoeft,

Hamburg, 21 October 1922

Dear Sir,

re FIRST ENTRY REPORT NO 15210

TIRADENTES

With reference to the First entry Report on this Vessel it is to be remarked that there is a hand pump fitted for pumping drinking water out of the peak tank but that there is no pumping connection for draining the Forepeak above the Peak tank deck although attention was called to this at the Builders the vessel left without a pumping connection for draining the forepeak above the peak tank deck hence the remark in the Interim Certificate

I am, Dear Sir

Yours faithfully

The Secretary

London

Geo. Dykes



© 2020

Lloyd's Register
Foundation

004789-004798-0032

17

72.

YOUNG BROTHERLY
LOVE GIL

The Geology of
Troms

the tank tank deck hence the tank in the Internal Certificate left without a pumping connection to draining the forepeak above. Although attention was called to this at the Entrance the vessel's connection to draining the forepeak above the Deck tank deck. It is to be remembered that there is a pump pump fitted for draining the tank tank deck but that there is no draining connection to the forepeak above the Deck tank deck.

LIBRARY
OF THE
LIBRARY OF THE
LIBRARY OF THE

Историческое значение

© 2020

Lloyd's Register
Foundation

© 2000 WILEY-LISSON, INC.