

F 2629

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name "DURHAM" Official No. _____

Port of Registry LONDON

This ship has been under survey at LONDON

on 12th June, 1959, and the following alterations to the conditions of assignment of loadlines have now been effected/~~found~~

RETAIN

No.1 Hatch on superstructure deck:-

Existing wood fore and aft locking bars now replaced by separate athwartship steel wires for each section of wood slab hatch cover, secured with rigging screws to welded eyeplates on deck.

*noted
21/7/59*

L.B. Morris

Surveyor to Lloyd's Register
of Shipping.

L.B. MORRIS.

A copy of this Report has been placed on board.

