

PT

~~COPY~~

18 JUN 1965

Ship's name "DURHAM"

Port LON

No 154055

Last survey date 29.4.65

Class is subject to

For conditions of class see previous endorsement.

ACTION is DEFERRED for S.S. by 10,65.

S.R.L. Appendix (as before ~~xxxxxxx~~)

Surveys due

SPECIAL SURVEY (C) due 10,64. Postponement
until 10,65 approved 4.11.64.

Nature of present survey (afloat ~~and in drydock~~)

Examination of chain cable. *Ship found to be short of 60 fms C.C.*

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed by

Recommendation SUBJECT to No.10 keel plate from fwd. (temporarily repaired 12,61) and to indented shell plate H.17 (p.s. from fwd) being specially examined and dealt with as necessary by the S.Sn, and to 60 fathoms of chain cable being supplied at the earliest opportunity, but ACTION be DEFERRED for S.S. by 10,65.

SUBJECT
AMENDED.

IN S.R.L. APPENDIX

Shell plates G.7, H.4, M.17 & 18
(p.s. from fwd) indented.

Shell plate L.9 (p.s) indented.
No.3 hold after bulkhead (s.s) slightly buckled.