



Lloyd's Register of Shipping

1600 Arch Street

Philadelphia, Pa.

May 2, 1941.

COPY

The Principal Surveyor,

New York, N.Y.

Motor Tanker "AMERICA SUN"
Phl. Report No. 7969

Dear Sir:

With reference to your letter of the 8th ultimo enclosing copy of a letter received from Wokingham dated 27th February last regarding the above case, I have to advise as follows:-

In reference to the stern bearing I am enclosing a blueprint showing length and design of stern bearing.

The 75 K.W. auxiliary oil engine was not built under Special Survey as according to the Rules any auxiliary below 100 HP does not require to be built under Special Survey. If required physical results of the 2 cyc. Diesel Engine driving the 75 K.W. generator can be furnished.

*See Section 2
clause 7 of
Rules for Heavy
Oil Eng.
L.Y.*

We are enclosing, in duplicate, two plans of the pumping arrangements as installed in the engine room.

With reference to the test certificates I am enclosing a letter received from the General Electric Co. which is self-explanatory and will you please advise whether we should go ahead and obtain test results of all motors installed in this vessel, which you will note will cost \$5.00 per motor.

In respect to electrical fittings, the protective covering in each case is armoured and leaded cables.

In respect to the safety valves, a drawing of the type safety valve fitted on all boilers is enclosed herewith.

© 2020

Yours very truly,

Lloyd's Register
Foundation

encl.

*P.S. Plans and drawing
sent under separate cover.*

M. W. Wokingham