

22 APR 1959

Received from Chief Ship Surveyor

SHIP'S NAME "HINDLEA" REPORT Cff. 60809.  
AR. No.

Outstanding Conditions of Class: Subject to set in side shell plating etc. (s.s.f) and top edge of shell plates C.4 & 5 (p.s.f) being dealt with as necessary by next S.S.

Endorsement of Certificate ~~(As before or None)~~

Nature of Present Survey: (Afloat and in dry dock)

Docking; W & T repairs; Damage (cause not stated) involving Nos. 1 & 2 keel plates from aft;

Recommendation:

SUBMITTED record of 'DS 3,59' be assigned SUBJECT as above and to indented keel plates Nos.1 & 2 from aft being specially examined and dealt with as necessary next drydocking.

DS 3,59. Subject.

*78*  
*15-A-59*



© 2020

Lloyd's Register  
Foundation