

30 AUG 1966

SM. Ship's name "STIRLINGSHIRE" Port Dar. No. 8/66Last survey date 1.7.66Class is subject toFor conditions of class see endorsement Mombasa dated 11.7.66.

ACTION is DEFERRED for S.S. by 8,66.

S.R.L. Appendix (as before ~~or none~~)Surveys due

SPECIAL SURVEY (C) due 2,66 - postponement until 7,66 approved 7.3.66. Further postpone-ment until 8,66 approved 9.5.66.

Nature of present survey (afloat ~~and in drydock~~)

Temporary repairs to wasted shell plate.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed by

TO NOTE		TRO
S. PLANS	S. RESEARCH	S. DEVELOP.
FREEDBOARD	E. REPORTS	PUBS.

Recommendation

SUBJECT to local corrosion on sternframe (s) and indented shell plate No.10 in 4th below sheer (p), indented shell plate etc., No. 7 from aft 3rd below sheer (s) and set in shell plates G.8 & H.7 (s from a) being specially examined and dealt with as necessary next drydocking, also to 15 fathoms of chain cable being supplied at the earliest opportunity, and to shell plate H.1 (s from a) being specially examined and dealt with as necessary by 10,66 but ACTION BE DEFERRED for S.S. by 8,66.

~~XXXXXX~~ SubjectIN S.R.L. APPENDIX

Sheerstrake plating abreast fore and main masts (p) set in.
(External cathodic protection fitted 2,64).
Shell plating (p & s) indented.