

COPY

LLOYD'S REGISTER OF SHIPPING



Port..... DAR ES SALAAM

Date..... 16th June, 1966.

Report No. 5/66

Invoice No. L.L. 504328

This is to Certify *that I have surveyed part of the machinery*
of the m.v. "Stirlingshire" MN.666 *gross tons* 6987
for examination of damage to steam driven main engine cooling
 water augmentor pump.

and that all my recommendations have been carried out to my satisfaction. I
am reporting accordingly and recommending to the Committee of Lloyd's Register
of Shipping that the machinery classification should be retained ~~and the following~~
~~xxxxxx records assigned~~

xx

Subject to repairs or renewals being carried
 out at Tanga or Mombasa to which ports the vessel
 is now bound, the said pumps being run at half
 speed during the voyage.

Parts now examined:—

R. P. [Signature]
 Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150° F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers, Servants or Agents of the Society."