

Ship's name

"ZEUS"

Port

11 - JAN 1963
Smk. No. 2075

GB Class is subject to set in shell plates No. 5 in 5th below and
Nos. 8 & 9 in 4th below sheerstrake (s.s.) (from fwd) being
permanently repaired on ship's arrival at a Japanese inland sea port
from present voyage.

S.R.L. Appendix (as before ~~xxxxxxx~~)

Nature of present survey (afloat and in drydock)

Docking: Wear and tear repairs:

Damage repairs (contact) - subject item.

Damage (cause not stated) involving shell plates H.8 & 9 (s.s.) and
structure in way.

Recommendation

SUBMITTED record of 'DS 11,62' be assigned,
subject to set in shell plates H.8 & 9 with
structure in way (s.s.) in way of E.R. being
specially examined and dealt with as necessary
by the Special Survey, but without other conditions.

DS 11,62 Subject
Amended
Without.

IN S.R.L. APPENDIX.

Shell plate E.6 (p.s.f) slightly indented.