

ed by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

EL'S NAME Steel S.S. "Erina" Rpt. Adl. No. 845

e remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

e of Survey

First EntryAwaiting Freeboard Report.

It is submitted, in the meantime, the Surveyor should be requested to state:—

- ① whether the spacing of the stiffeners on the after peak bulkhead is the same as in the sister vessels, and not as reported,
- ② whether the riveting of the upper dk. stringer is as approved,
- ③ whether the spacing of the rivets in the bottom longitudinals is as approved and not as reported,
- ④ whether the depth of the side transverses forward is as approved and not as reported.

10/5/23

 © 2020
Lloyd's Register
Foundation
[Signature]
9/5/23.