

LLOYD'S REGISTER OF SHIPPING

Port Khorramshahr.19th July, 1960.**This is to Certify** *that I have*

Surveyed the Machinery of the ss. "WORLD SKY" 12862 tons gross of Monrovia for damage stated due to grounding in the Shatt Al Arab river after leaving No.11 Jetty, Abadan on the 14/15th. July 1960 on loaded voyage to Port Sudan.

*and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will **Recommend** that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book*

and that her Machinery Classification Record be continued in the Book, subject to the propeller and after and of the stern bush being specially examined at the next drydocking (grounding) and to all other conditions at present attached to the machinery's class being dealt with as previously recommended.

Parts now examined:

(C.S. Items only)

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."