

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee London Telex
Telex No.: 24305

Telephone: ROYal 9166

2nd October, 1959.

ssn(S)
LME

Dear Sirs,

Steamer "MOUNT OLYMPUS"

The Society's Surveyor at Port Elizabeth has reported that this ship was under survey in July when the Boiler Survey was partly held.

Some temporary repairs were carried out to the combustion chamber backplate stays in the port and starboard main boilers, but it was recommended that these stays should be permanently repaired by the end of December, 1959. The Committee have continued the class subject to this matter receiving attention by that time. I shall be glad if you will let me know, in due course, when and where this work will be carried out.

In order to complete the Boiler Survey the centre boiler requires to be examined throughout and its safety valves adjusted under steam. Your proposals in this respect also are desired.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

The Mount Olympus Shipping Company,
c/o Rallis Shipping Co.Ltd.,
Bevis Marks House,
Bevis Marks,
LONDON, E.C.3.



© 2021

Lloyd's Register
Foundation

005013-005019-0178