


"SAENTIS"

IT IS SUBMITTED that before this case receives consideration, the Surveyor should state if the forward and aft entablatures of the starboard main engine which are recommended to be renewed by 4.53 have been dealt with.

Also as the Surveyor has recommended a new CS date, should be informed that according to our records, the examination of the following machinery parts is still outstanding and he should be requested to state if any of these parts have been examined at this time.

- The starboard main engine scavenge pump, ✓
- The starboard aft auxiliary engine 70kW,
- The electrically driven air compressor,
- The four auxiliary starting air receivers,
- The electrical installation, ✓
- The pumping arrangements,
- The ballast pump,
- The General Service pump.



~~Check list:~~
(Early ready)

005013- 005019- 0242

head covers, valves & valve gear. Thrust block & bearings. Bed plate & holding down bolts.