

date I have the pleasure to enclose herewith freeboard

BOARD REPORT on the

*B. S. "Memphis".*

It is submitted the Surveyor be informed that it has been assumed the thicknesses of the sides of Nos 1, 2 and 3 Hatchways are .54, .52 and .44 respectively and not .34 as given on his report, but he should confirm these

*W.D.*

*S. W.B.*

*3-9-23*

*Completed*



© 2021

Lloyd's Register  
Foundation

005029-005037-0216

005029-005037-0217