

GLASGOW REPORT No. 62389.

Port of GLASGOW.

8th. May. 19 40.

REPORT ON MASTS, SPARS, AND RIGGING.

Sirs,

Having, in accordance with your instructions,
examined the Masts, ~~Spars~~, ~~Iron Work~~ of same, and Rigging, of the
vessel) S.S. "TENNESSEAN". NOW "EMPIRE PENGUIN"

Date of examination) 3rd. May. 19 40.,

I report that I found Fore lowermast and topmast in good
condition, ascertained by hammer test.

For rigging four shrouds in good condition, four shrouds in
poor condition being renewed, lower stays in good condition,
mainmast backstays in good condition, topmast stay in bad
condition being renewed,

For rigging two shrouds in good condition Six shrouds in bad
condition being renewed, lower stay being fitted, two topmast
stays in good condition, topmast stay being fitted.

Foremast and topmast in good condition, ascertained by hammer

O. O.

Surveyors,
Register of Shipping,

GLASGOW.



B. Caldwell 2019

Repairs effected 14/5/40.

Geo. Lockhart.

005047-005055-0145

Observations, Opinion as to Class, Recommendation, etc.