

AC
LVA
PAE

WRECK
SECTION
No. 1069

1069

J	J
F	F
M	M
A	A

WRECKED

17
17

M	M
JE	JE
JY	JY
A	A
S	S
O	O
N	N
D	D

WRECK
SECTION
No. 1069



© 2020

Lloyd's Register
Foundation

005056-005060-0043

British

MN1430

SS 5/62

SS 5/62	1953-9	Greenock Dkyd Co. Ltd.—Grk	M Tanker	Mcny. art
	546' 7"	69' 4"	29' 10 $\frac{1}{2}$ "	21 Ta
	512' 0"	69' 0"	38' 6"	
EL g $12\frac{3}{16}$ SQ	P119' B48' F56'	1 dk, 2nd dk clear of cargo tanks	1 Ha (stl)	
	RW 17B		Der 4(5)	
	rf 4" WB170t			

Oil 2SA 6Cy. 670 × 2320 mm
7150bhp Doxford
Scott's S.B. & Eng. Co. Ltd.
2AuxB 220t
3 × 40kW 110V d.c.

1432t (hvf)
Grk
14k

Enquiries to The Shipping Management, S.A.M.
27 Boulevard d'Estee.
[Monte Carlo.
Monaco.
Boite Postal 130.

[illegible]