

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

4th January, 1966.

R.
JMC/DET

Dear Sirs,

M.S. "ALVA CAPE"

With reference to the Continuous Survey cycle of the machinery, I would inform you that according to the records in this Office, the following items have not been seen by the Society's Surveyors for more than four years, and I shall be glad to learn what early arrangements are proposed to be made regarding their examination:-

Main Engine Nos.6 centre connecting rod,
top end and guide.
Main engine Nos.1, 2, 3 and 6 side and
No.3 centre crankpins and bearings.
H.P. fuel injection pump
Both main air receivers and their relief devices

The Auxiliary Boiler Survey became due at the end of July 1965, and to complete this inspection for the record A.B.S. 7.65 the safety valves of both auxiliary boilers require to be adjusted, and the oil burning system and remote controls examined under working conditions. I shall be glad to learn what arrangements are proposed to be made regarding the completion of this inspection.

Yours faithfully,

Clerk to the
Classification Committee

The Shipping Management S.A.M.
27, Boulevard d'Italie,
Post Office Box No.130,
MONTE CARLO,
Monaco.

Lloyd's Register
Foundation

005056-005060-0071