

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

9th September, 1964

C  
DNS/RW

Dear Sirs,

m.v. "ALVA CAPE"

A Report of the survey carried out by the Society's Madras Surveyors between the 17th and 20th ultimo, has now received the consideration of the Committee.

At that time, Metalock repairs were effected to the main engine No. 3 cylinder liner, which was found to be cracked, and it was recommended that this item should be specially examined and dealt with as necessary by the end of November, 1964.

The Committee have continued the vessel's class subject, inter alia, to this matter receiving attention by that time.

Yours faithfully,

pro Clerk to the  
Classification Committee

The Navigation & Coal Trade Co. Ltd.,  
Billiter Buildings,  
22, Billiter Street,  
LONDON E.C.3

© 2020  
Lloyd's Register  
Foundation

005056-005060-0114