

ass is subject to

the donkey boiler not being used until surveyed.

4E

11 NOV 1960

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME....."LIBERTY S. EMBIRICOS".....REPORT.....BMN.....No. 4921.

Repairs effected main condenser.

IT IS SUBMITTED that this vessel is
eligible to remain as classed subject as above.



© 2020

[Signature]

Lloyd's Register
Foundation

10.11.60.

005056 - 005060 - 0175