

REPORT OF SURVEY ON SHIPS CLASSED FOR GREAT  
LAKES AND ASSOCIATED SERVICES

Received London

1 JUL 1963

Ship's Name SS/MS "WINNIPEG"

Gross tons 2383

Is there a rpt. 9? Yes

Port Toronto

Rpt. No. 4722

No. of visits One

First date and

Last date 26-4-63

Interim Cert. issued  
& copy herewith? NoDamage rpt. issued  
& copy herewith? No

Last rpt. (H.Q. only)

14643 MTL

Date of  
completing rpt. 30-4-63

Surveyed at, if different from Port above

Surveyed afloat  
and/or in D.D. Afloat

Last date of examination in D.D.

Has a Load Line  
Survey been held? Yes (Annual)

Freeboard Marks verified Yes

State which additional Rpt. 8 is attached: (Cont); (DR); (EQ); (Rig)

Survey fees \$40.00

Damage fee

Expenses \$10.00

R.F.B. No. Tto-635 May 6/63

S.A. fee

I/we have surveyed the above ship in accordance with the Rules for Lake Annual Survey

## Examined &amp; Condition

## Examined &amp; Condition

Holds, incl. blkhd.,  
inner btm. plating, etc

Good

Pumps & pumping arrgts.  
outside mchy. space

Good

Bilges &amp; ceiling

Good

Steering arrgts. incl. gear

Good

'Tween decks

Good

W.T. doors &amp; sluice valves

Good

Deck &  
deck erections

Good

\*Ventilators

Good

Machinery space

Good

\*Hatchways

Good

Under E. &amp; B.

Good

\*Casings &amp; companionways

Good

Masts, rigging &  
outfit

Good

\*Superstructures

Good

Windlass &  
hawse pipes

Good

Guard rails &amp; freeing ports

Good

\*Air & sounding  
pipes

Good

Overboard discharges, ash  
chutes & other shell openings

Good

Examined &  
conditionTested &  
conditionExamined &  
conditionTested &  
condition

Peaks

Good

Tankers

Cargo tanks

Cofferdams

Pump rooms

Side tanks in hold

Deep tanks

Has a grain survey  
been held?

No

Has a damage survey been held?

No

The items now surveyed are detailed on this report. All were found or placed in good order unless otherwise stated.

I/we recommend that this ship remain as classed with fresh record of Annual Survey. 4/63

(Where conditions of class are recommended to  
be retained, imposed, amended or deleted, particulars  
must be stated above and on the interim certificate.)

L.D. MacBean

Surveyor(s) to Lloyd's Register of Shipping

Date of Committee

Minute

As shown

As 4/63

MBS 4/63.

THURSDAY 4 JUL 1963

Lloyd's Register  
Foundation

005061-005068-0116

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

action taken or recommended should be  
described fully under "defects & repairs".  
When any part has been subjected to  
pressure test this should be stated.date of the next Special Survey  
repairs have been effected or is considered  
that re-examination or repairs should be  
made before that date the circumstances andThe condition of any item is to be described  
as "good" only when it has been examined,  
found or placed in good condition and is  
considered to be acceptable until the due

\*These items to include their closing appliances