

Main Air Compressors

- 12 piston rings for each piston
- 1 set of crosshead pin bearings (complete) with bolts
- 1 crosshead pin
- 1 set crankpin bearings (complete) with bolts
- 1 complete set of valve seatings, guards & springs for L.P., M.P. and H.P. compressor.
- 10 suction valves for each stage
- 10 delivery valves for each stage
- 1 cylinder liner for each stage
- 1 cooler stack for each stage.

Lubricating oil and Piston Coolers

- 1 cooling stack for cooling water cooler
- 1 " " " lubricating oil "

Turning engine

- 1 spare armature complete in watertight box
- 1 complete set of brush holders and brushes.

F. W. Benson



© 2020

Lloyd's Register
Foundation