

COPY

LLOYD'S REGISTER OF SHIPPING



Port SOUTHAMPTON.

Port SOUTHAMPTON.

9th December, 1957.

28th November, 1957.

This is to Certify that I have

This is to Certify that I have

Surveyed the S.S. "WILLIAM CASH", 1186 tons gross of London, whilst the vessel lay in drydock and on a slipway at Southampton on the 7th November, 1957, and subsequently for dry docking on account of damage to the rudder stated sustained due to the vessel striking an unknown submerged object whilst leaving Dibbles Wharf, Southampton, on the 6th November, 1957; Damage to foremast stated sustained due to fall slipping on the windlass drum whilst lowering mast & mast falling onto the hatch; Damage to port quarter shell plating stated sustained due to the vessel contacting the knuckle at the entrance to No. 4 Drydock, Southampton, on the 8th November, 1957.

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all repairs

recommended by me have been completed to my satisfaction, and

that I have Recommended that she be retained as classed

in the Register Book with fresh record of D.S.11,57 subject to the Recommended that the record of upper gudgeon being examined at next Drydocking and indented shell

plates D.4 and E.4 (p.s.a.) being further examined and dealt with as necessary at the vessel's next Special Survey,

being fit to carry dry and perishable cargoes.

Albert E. Ferrington


Surveyor to Lloyd's Register.

A.E.FERRINGTON.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Port. B.) 70m.4.56. (MADE AND PRINTED IN ENGLAND.)



Lloyd's Register
Foundation

005075-005081-0118

005075-005081-0117