

2 FEB 1960

by Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME "MIRADOR" REPORT Ist. No. 4772

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/62.)

The ISTANBUL Surveyors report (1,59) this tanker undergoing damage repairs due to an explosion and subsequent fire. During this time the ship had a second explosion and subsequently sank on the 12th January (see cablegram dated 14.1.59).

Expl 13th sank 12th.
11.15am 4am

The case is submitted for the information of the Committee.

DA. 30/1/59.



© 2020

Lloyd's Register
Foundation

005082-005088-0041