

t to Chief Surveyors.....

Received from Chief Surveyors.....

G<sup>B</sup>

"HOLDERNESS"

REPORT

Gls.

No. 89666

SHIP'S NAME.....

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

ture of Survey..... Docking: Permanent/deferred ~~XXXXXXXX~~  
 damage repairs. When due.....

NOTE D.

Subject to set in shell plates D.3 & E.3 (s.s.f) also D.4 & E.3 etc. (p.s.f) being dealt with at the Special Survey.

IN S.R.L. APPENDIX

Shell plates F.2 & 3 (s.s.f) and sheerstrake plates Nos. 2 & 3 and No.3 in strake below (p.s.f) indented.

ABM,  
3-2-59.



© 2020

Lloyd's Register  
Foundation

005107-005117-0255