

4E

13 AUG 1958

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME..... GASCONY

REPORT

Lon

No. 138351

The Surveyor reports some damage to the main engine blast air compressor and to the port after generator and repairs put in hand but not proceeded with as, upon Owners' instructions, arrangements made for the vessel to be towed to Hamburg. No Interim Certificate for the voyage in tow was requested.

IT IS SUBMITTED that this case be deferred pending receipt of report from the Hamburg Surveyors.



© 2020

Lloyd's Register
Foundation

13.8.58

005132-005140-0196