

6 E

Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

NAME "BARENDRECHT" Rpt. Lon. No. 109228

arks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Survey _____ DAMAGE TO ENGINES AND BOILERS.

This vessel is reported by the London Surveyor
to have sustained damage to by bombs. through

Temporary repairs have been effected to his satisfaction to enable her to proceed on her voyage to the Tyne.

The Surveyor recommends repairs be carried out as necessary on arrival in the Tyne.

It is submitted action be deferred.

© 2020
Lloyd's Register
Foundation

9.12.40.

005132-005140-0222