

E-5 MAY 1952

Received from Chief Ship Surveyor

SHIP NAME TEMPO REPORT Sld. No. 35776

Standing Conditions of Class: Subject to permanent repairs to indented shell plates E.4 & F.4, etc. (s.s.f.) by the next Special Survey.

Assessment of Class (B) (~~As before~~ or None)

Where of Present Survey: (Afloat and in dry dock)

Docking:  
Damage - cause not stated.  
Conversion to oil  
burning.

Recommendation: SUBMITTED record of docking 2,52 be assigned, subject as above.

2,52 Sld. Subject

INSERT IN R.B.

✓ "Fitted for oil fuel 3,52 F.P. above 150°F"  
DTa O.F.



© 2020  
W.O.T.  
24. 4. 52

Lloyd's Register  
Foundation

005174-005174-0040