

Ship's name

Tassia

Port

han

No.

156110

Class is subject to

Last survey date

7.3.66

① evaporator not being used until surveyed.
Docking W/D 0.11" remounted to 0.025"

Tailshaft drawn due to a rope having fouled the propeller. Shaft crack detected & in order. Slight corrosion noted in way of oil gland, corrosion marks polished away. Shaft diameter in way of corrosion marks greater than the diameter at the top of the cone.

It is submitted that this vessel is eligible to remain as CLASSED.

TS (CG) 3.66 max

subject as above



© 2020

Lloyd's Register
Foundation

005174-005179-0250