

EA

9 MAR 1965

Ship's name "TASSIA"

Port

HAM.

No.

14301

Last survey date 24.12.64.

Class is subject to

indented shell plating (p.s) and indented stem plating in way of 13' draft mark being specially examined and dealt with as necessary next drydocking, and to 45 fathoms of chain cable (supplied 1962) being verified with test certificates at the earliest opportunity.

S.R.L. Appendix ~~(as before)~~ none)

Surveys due

SPECIAL SURVEY (C) due 5,65. Postponement until 5,66, approved 2.2.65 provided a satisfactory G.E. is held in drydock.

Nature of present survey (afloat ~~and in drydock~~)

Equipment - loss of bower anchor and 15 fathoms of chain cable.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS.

SS proposed to be completed by

Recommendation

SUBJECT as above and to a bower anchor and 15 fms. of chain cable being supplied at the earliest opportunity.

As Now Subject

S.P.B.
12/2/65



© 2020

Lloyd's Register
Foundation