

6 - MAR 1964

Ship's name TASIA

Port Lisbon

No. 10418

Last survey date 29.1.64

Class is subject to

1. Evaporator not being used until surveyed.
2. Superheaters of both boilers be renewed at earliest opportunity.

On account of contamination of the feed water by salt water
Condenser enamelled and a number of leaking tubes now
plugged, boiler cleaned on water side and some mountings
and feed pipes enamelled and overhauled where necessary
Some wear & tear repairs effected.

The ballast pump water end enamelled and defective valve
seats found plugged with wood. also various parts of the
suction & delivery valve units found missing. also the
division plates eroded. The Surveyor recommends
the ballast pump water end be renewed at the next
Special Survey

It is submitted that this
vessel is ~~to~~ to remain
as CLASSED.

Subject as above
and as now
recommended.

Le
6/3/64



© 2020

Lloyd's Register
Foundation