

4 - FEB 1964

EA
Ship's name "TASSIA" Port ABO. No. 1023

Last survey date 14.12.63

Class is subject to

indented shell plating (p.s) and indented stem plating in way of 13' draft mark being specially examined and dealt with as necessary next drydocking, and to 45 fathoms of chain cable (supplied 1962) being verified with test certificates at the earliest opportunity.

S.R.L. Appendix (~~as before or~~ none)

Nature of present survey (afloat ~~and in drydock~~)

Renewal Load Line Survey.

Recommendation SUBJECT as above.

As Now Subject.



© 2020

Lloyd's Register
Foundation

Handwritten: J.F.L.
23-1-64
x