

COPY

Ship's name

TASSIA

Port

Hamburg

No.

14301

Last survey date 24.12.64

Class is subject to

- 1 Evaporator not being used until surveyed
- 2 IP Piston valve (metalocked 4.64) being hammed by 10.64

SRL - Subject item 2 hammed & 4 locks found loose - these locks now renewed & Surveyor recommends that the IP piston valve (metalocked 4.64 & 12.64) be specially hammed by 12.65.

Machy Reps - New LP slide valve rod fitted & straps reinstalled.

It is submitted that this vessel is eligible to remain as CLASSED

subject as above for item 1 & as now amended item 2



© 2020

Lloyd's Register
Foundation